



Weld Spring Hangers to mainframes
with 180 Amp minimum!

(Hangers 50 x 40 x 10, drilled
centrally M16 or similar)

Scale 1 : 2 @ A4